## Annex G

## **Investigation Report**

## **Investigation Report of CEMS Exceedances**

Date	1 – 30 June 2021
Time	Continuous monitoring throughout June 2021
Monitoring Location	Continuous Environmental Monitoring System (CEMS)
Parameter	Various emission parameters of the Cogeneration Unit (CHP)
	and Ammonia Stripping Plan (ASP)
Exceedance Description	1. Continuous monitoring was carried out at the CAPCS, CHP and ASP throughout the reporting period using the CEMS. According to the EM&A Manual, exceedance is considered if the emission concentration of the concerned pollutants is higher than the emission limits stated in Tables 2.2, 2.3 and 2.5 of the EM&A Manual (Version F) for CAPCS, CHP and ASP respectively. The concentration of the concerned air pollutants were monitored on-line by the CEMS. Exceedances of various emission parameters were recorded on the CEMS
	<ul> <li>including:</li> <li>NO<sub>x</sub>, SO<sub>2</sub>, VOC and HF in the CHPs</li> <li>CO, NO<sub>x</sub> and NH<sub>3</sub> in the ASP.</li> </ul>
	2. According to the Contractor, exceedance is observed to occur mainly at CHPs operated at loading with 40-60% of the optimal loading (1400KW)
	3. The Contractor explained that the NO <sub>x</sub> exceedances recorded in CHP 1 and 2 were due to the low biogas loading which resulted in the poor performance efficiency in CHP.
	4. The Contractor explained that the NO <sub>x</sub> , VOC and HF exceedances recorded in the CHP 3 were due to the unstable performance of the CHP. Although the Contractor was advised to halt the use of CHP 3 in this reporting period due to its unstable performance since the last reporting period, it was used when CHP 2 was under urgent maintenance as sufficient biogas consumption requires the operation of 2 CHPs.
	5. The Contractor explained that the CO, NO <sub>x</sub> , VOC and NH <sub>3</sub> exceedances in ASP were caused by unstable column temperature in the thermal oxidiser, which have led to incomplete combustion of biogas and NH <sub>3</sub> in ASP.
	6. The SO <sub>2</sub> exceedances recorded in CHPs were due to power disruption and tripping of the desulphurisation system, which were stopped temporary for urgent maintenance. The desulphurisation system resumed to normal operation after the provision of power resumed to normal and on the day after urgent maintenance.
Action Taken / Action to be Taken	<ul> <li>The quantity of SSOW has increased with the help of the EPD in this reporting month, which has led to an overall drop in no. of hours of exceedance from the last</li> </ul>

Remedial Works and	reporting period (from 193 no. to 123 no. of hours). The Contractor will continue to actively liaise with EPD in their monthly meeting with an aim to increase the quantity of SSOW that can be treated daily, such that sufficient biogas can be generated for the CHP to be able to operate at optimal efficiency.  • The Contractor has engaged with the CHP supplier to carry out an on-site inspection for CHP 1 and 2 by the supplier representative on 14 June 2021. The Contractor will continue to avoid the use of the CHP3 in the coming months when possible. An inspection and overhaul of CHP3 is scheduled in July.  • The Contractor has been fine-tuning the temperature of the thermal oxidiser to optimise its performance.  • The Contractor has established a regular communication channel with the overseas ASP supplier, to overcome the fact that the supplier cannot travel to Hong Kong due to travel restriction.  • The Contractor arranged for remote fine-tuning of the ASP with the overseas ASP supplier during this reporting period.  • Daily meetings have been held to review ASP operational and emission data.  • The Contractor will continue to arrange for remote fine-tuning of the ASP with the overseas contractor in the upcoming reporting period. The Contractor will continue to carry out maintenance measures as per the supplier's manual.  • The Contractor in consultation with the overseas ASP supplier will investigate the reasons for the occasional equipment tripping that has led to unstable column temperature of the thermal oxidiser. The Contractor may carry out replacement of some ASP equipment and/or increase maintenance frequency, subject to their investigations.
Follow-up Actions	processes, including the modification works and follow-up emission monitoring of the CHP and ASP to avoid exceedance.  MT has advised that the issue of emission exceedances should be prioritised in up-coming meetings. MT will carry out follow-up audit regarding the progress next month.

Prepared by: Angela Yung, MT Representative
Date 14 July 2021