# Annex F

# **Investigation Reports**

#### Annex F1

# Investigation Reports for October 2022

# **Investigation Report of CEMS Exceedances**

Date	1 – 31 October 2022
Time	Continuous monitoring throughout October 2022
Monitoring Location	Continuous Environmental Monitoring System (CEMS)
Parameter	Various emission parameters of the Cogeneration Units (CHP) and
	the Ammonia Stripping Plant (ASP)
Exceedance Description	<ol> <li>Continuous monitoring was carried out at the CAPCS, CHP and ASP throughout the reporting period using the CEMS. According to the EM&amp;A Manual, exceedance is considered if the emission concentration of the concerned pollutants is higher than the emission limits stated in Tables 2.2, 2.3 and 2.5 of the EM&amp;A Manual (Version F) for CAPCS, CHP and ASP respectively. The concentration of the concerned air pollutants were monitored on-line by the CEMS. Exceedances of various emission parameters were recorded on the CEMS including:         <ul> <li>NOx and SO<sub>2</sub> from the CHPs</li> <li>NOx and NH<sub>3</sub> from ASP</li> </ul> </li> <li>The Contractor has investigated the cause of the exceedance and identified that         <ul> <li>The exceedances of SO<sub>2</sub> from the CHPs occurred due to tripping of the de-sulphurisation system resulted from the residue of sulphur accumulated at the exhaust heat exchangers.</li> <li>The exceedances of NO<sub>x</sub> from CHPs occurred due to system instability caused by prolonged usage of the CHPs.</li> <li>The exceedance of NOx and NH<sub>3</sub> from ASP occurred due to system instability caused by ASP column and heat exchanger deteriorated condition.</li> </ul> </li> </ol>
Action Taken / Action	The Contractor has arranged cleaning of the heat exchangers of all
to be Taken	CHPs to remove potential sulphur residue from the exhaust gas system. The Contractor has also replaced all catalytic convertors with an aim to improve the CO removal efficiency of the system.  The Contractor has arranged cleaning of the ASP column and heat exchanger to resume performance.
Remedial Works and	The Contractor has arranged a specialist to review the CEMS
Follow-up Actions	system performance and accuracy. The specialist will carry out indepth investigation and propose any remediation needed.
	The Contractor is recommended to closely monitor the processes, including the modification works and follow-up emission monitoring of the ASP to avoid exceedance.

### OSCAR Bioenergy Joint Venture EP/SP/61/10 - Organic Resources Recovery Centre Phase 1

The Contractor should review the routine inspection and
maintenance schedule of the ASP and conduct preventative maintenance to avoid similar re-occurrence of the equipment
failure.

Prepared by: Chris Ng, MT Representative

Date 13 November 2022

#### Annex F2

Investigation Reports for November 2022

#### **Investigation Report of CEMS Exceedances**

Date	1 - 30 November 2022
Time	Continuous monitoring throughout November 2022
Monitoring Location	Continuous Environmental Monitoring System (CEMS)
Parameter	Various emission parameters of the Cogeneration Units (CHP)
Exceedance Description	<ol> <li>Continuous monitoring was carried out at the CAPCS, CHP and ASP throughout the reporting period using the CEMS. According to the EM&amp;A Manual, exceedance is considered if the emission concentration of the concerned pollutants is higher than the emission limits stated in Tables 2.2, 2.3 and 2.5 of the EM&amp;A Manual (Version F) for CAPCS, CHP and ASP respectively. The concentration of the concerned air pollutants were monitored on-line by the CEMS. Exceedances of various emission parameters were recorded on the CEMS including:         <ul> <li>NOx, SO<sub>2</sub> and HCl from the CHPs</li> </ul> </li> <li>The Contractor has investigated the cause of the exceedance and identified that         <ul> <li>The exceedances of SO<sub>2</sub> from the CHPs occurred due to tripping of the de-sulphurisation system resulted from the residue of sulphur accumulated at the exhaust heat exchangers.</li> <li>The exceedances of NO<sub>x</sub> from CHPs occurred due to system instability caused by prolonged usage of the CHPs.</li> <li>The exceedance of HCl form CHP 2 occurred due to system instability caused by CHP 2 column and heat exchanger deteriorated condition.</li> </ul> </li> </ol>
Action Taken / Action to be Taken	The Contractor has arranged cleaning of the heat exchangers of all CHPs to remove potential sulphur residue from the exhaust gas
	system. The Contractor has also replaced all catalytic convertors with an aim to improve the CO removal efficiency of the system.
Remedial Works and Follow-up Actions	The Contractor has arranged a specialist to review the CEMS system performance and accuracy. The specialist will carry out indepth investigation and propose any remediation needed.

Prepared by: Chris Ng, MT Representative

Date 13 December 2022