Annex F

Investigation Report

Date	1 – 31 October 2023
Time	Continuous monitoring throughout October 2023
Monitoring Location	Continuous Environmental Monitoring System (CEMS)
Parameter	Various emission parameters of Cogeneration Units (CHPs) and
	Ammonia Stripping Plant (ASP)
Exceedance Description	 Continuous monitoring was carried out at the CAPCS, CHP and ASP throughout the reporting period using the CEMS. According to the EM&A Manual, exceedance is considered if the emission concentration of the concerned pollutants is higher than the emission limits stated in Tables 2.2, 2.3 and 2.5 of the EM&A Manual (Version F) for CAPCS, CHPs and ASP respectively. The concentrations of the concerned air pollutants were monitored on-line by the CEMS. Exceedances of various emission parameters were recorded on the CEMS including: NOx, SO₂ and HCl from CHP1; NOx and SO₂ from CHP2; NOx and SO₂ from CHP3; and NOx, SO₂ and NH₃ from ASP. The Contractor has investigated the cause of the exceedances and identified that: The exceedances of NO_x, SO₂, and HCl from the CHPs, as well as the exceedances of NO_x, SO₂ and NH₃, from ASP occurred due to system instability.
Action Taken / Action	The Contractor investigated the reason for the exceedances and
to be Taken	arranged Remedial Works and Follow-up Actions (see below).
Remedial Works and	The Contractor had arranged the CHP supplier to inspect, analyse
Follow-up Actions	and improve CHP and ASP performance in November 2023 based
	on final reports of the quality assurance level 2 test (QAL) for the
	CEMS calibration. This QAL2 evaluation is still ongoing, and
	improvement recommendation will be provided once the final
	report is received.

Investigation Report of CEMS Exceedances

Prepared by:	Alex Khawaja Waheed, MT Representative
Date	10 November 2023

EP/SP/61/10 – Organic Resources Recovery Centre Phase 1

Date	12 October 2023
Monitoring Location	Petrol Interceptor 2
Parameter	Suspended Solids, Chemical Oxygen Demand, Oil & Grease
Exceedance Description	 According to EM&A Manual, the monitoring of the effluent discharge from the outlet chamber of the Effluent Storage Tank and Petrol Interceptors shall be carried out monthly and bi-monthly, respectively, under Section 21 of the Water Pollution Control Ordinance (WPCO) license. Exceedance is considered if the concentration of discharged effluent sample from the Effluent Storage Tank and Interceptors is higher than the discharge limits stated in Part B2 of the WPCO. Exceedances of discharge parameter were recorded during the monitoring of effluent discharge from the Petrol Interceptor 2 (Suspended Solids, Chemical Oxygen Demand, Oil & Grease). The Contractor has investigated the cause of the exceedances and found that: The exceedances of Suspended Solids, Chemical Oxygen Demand and Oil & Grease from the effluent discharge from Petrol Interceptor 2 occurred due to the increasing road cleaning frequency, leading to Suspended Solids, Chemical Oxygen Demand and Oil & Grease in the sample taken on 12 October 2023.
Action Taken / Action to be Taken	Proper cleaning of the petrol interceptor was arranged to maintain a better effluent water quality. Additionally, after measures
	implemented by the Contractor, a second Discharge Sample from
	the Petrol Interceptor 2 was collected on 31 October 2023 as a
	follow-up, with all parameters recorded to be in compliance with
	discharge limits.
Remedial Works and	The Contractors will review the efficiency of the Petrol Interceptor
Follow-up Actions	to ensure the discharge effluents comply with the discharge limits.

Investigation Report of Discharged Sample Exceedances

Prepared by:Alex Khawaja Waheed, MT RepresentativeDate3 January 2024